

Oil Field Environmental Incident Summary

Incident: 20131005193223 **Date/Time of Notice:** 10/05/2013 18:56

Responsible Party: Hess Corporation

Well Operator: HESS CORPORATION

Well Name: EN SOUTH HORST 50-93 BAKKEN FACILITY

Field Name: ROBINSON LAKE

Well File #: 0

Date Incident: 10/5/2013 **Time Incident:** 14:35

Facility ID Number: 219074-01

County: MOUNTRAIL

Twp: 154

Rng: 93

Sec: 21

Qtr: SW SE

Location Description:

Submitted By: Courtney Wilhelm

Received By:

Contact Person: Courtney Wilhelm
3015 16TH ST SW STE 20
MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Miles

Distance Nearest Water Well: 0.5 Miles

Type of Incident: Tank Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units
Oil	5.25	barrels	5	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

Followup **Units**

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Visual impacts to ground surface.

Action Taken or Planned:

Gasket was replaced, Vac truck was dispatched to vac up oil inside the berm, Visual impacts will be cleaned up and disposed of.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 10/7/2013 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location, according to the report.